



LPS Facility Assessment

The next 25 years

March 2012 to March 2037

ES Current Facility Status 2012

- ▶ **ADA – fully compliant**
 - ▶ All restrooms completely renovated
- ▶ **HVAC – completely renovated**
- ▶ **All roofs – 25 year life expectancy**
- ▶ **Energy Efficient**
 - ▶ Solar panels
 - ▶ Insulated roofs
 - ▶ New insulated windows
 - ▶ Water efficient restroom fixtures

ES Facility Assessment for Future Needs

- ▶ **Media Centers** Referendum/Capital Improvement (R/CI)
 - ▶ Collins, Riker, Harrison
- ▶ **Large, second gymnasium space** R/CI
 - ▶ Riker, Mount Pleasant
- ▶ **Gymnasiums with AC** R/CI
 - ▶ Collins, Burnet Hill, Hillside, Harrison
- ▶ **Small Activity Rooms** R/CI
 - ▶ Riker, Mount Pleasant
- ▶ **Enrollment Capacity** R/CI
 - ▶ See Demographic report

MS Current Facility Status 2012

- ▶ **ADA – fully compliant**
 - ▶ All restrooms completely renovated
- ▶ **HVAC – completely renovated**
- ▶ **All roofs – 25 year life expectancy**
- ▶ **Energy Efficient**
 - ▶ Solar panels
 - ▶ Insulated roofs
 - ▶ New insulated windows
 - ▶ Water efficient restroom fixtures
- ▶ **Auditoriums completely renovated**
- ▶ **MS capacities will meet all future enrollment projections**

MS Facility Assessment for Future Needs

- ▶ **Gymnasiums with AC R/CI**
 - ▶ Mount Pleasant Middle School 1 gym
 - ▶ Heritage Middle School 2 gyms

High School Current Facility Status 2012

- ▶ ADA – accessible
- ▶ AC added to all spaces in 2008
 - ▶ Exception, old gym to be completed summer 2012
- ▶ Energy efficient 2008 additions (LEED certified)
 - ▶ Solar panels
 - ▶ Insulated roofs
 - ▶ Insulated windows
- ▶ Auditorium renovated
- ▶ HS capacity will meet all future enrollment projections

HS Facility Assessment for Future Needs

- ▶ **Roofs CI**
 - ▶ 3 year replacement plan
- ▶ **Bathrooms R/CI**
 - ▶ Renovate for full ADA compliance
- ▶ **Space Conversions CI**
 - ▶ Remove photography labs to enlarge art rooms
 - ▶ Renovate Guidance Suite
 - ▶ Renovate and convert old TV studio

Other Facility Status

- ▶ **Alternative High School** LPS/Livingston Township shared solution
 - ▶ Classroom standards do not meet the conditions of all other LPS facilities
 - ▶ Lighting, HVAC, electrical/data wiring
 - ▶ ADA – not compliant
 - ▶ Bathrooms, elevator, access points
- ▶ **Vehicular Fleet** LPS/Livingston Township shared solution
 - ▶ Storage and maintenance inadequate
- ▶ **Foxcroft Central Office** CI
 - ▶ ADA – not compliant
 - ▶ Bathrooms, elevator, access points
 - ▶ Extremely energy inefficient—1968 construction
 - ▶ Roof replacement needed
 - ▶ Window and door replacement needed